OCZ Firmware Release Notes

Vertex 3 series, Vertex 3 Max IOPS series, Agility 3 series, Solid 3 series

Version 2.15

Issues resolved since version 2.13:

- Fixed a rare condition that may cause Windows Blue Screen error when the primary-configured drive woke up from either a SATA slumber mode or S3/S4 modes

- Fixed a rare condition that may cause Windows Blue Screen error when the drive was configured as primary with OS installed

- Fixed a corner-case issue that may cause the drive to stutter or Windows freezing screen when a media read error occurred

- Further improved robustness of Secure Erase operation to prevent possible low-level data structure corruption

- Significantly improved TRIM handling to enhance system stability

Known open issue:

- Formatting a RAID1 volume takes longer than expected with PMC-Sierra BR-8 HBA

www.ocztechnology.com